

**Work Order 4-14750**

Date: 2025-05-15

Finalized

Service Order

18006

318-792-5177

Alexandria - Consolidated Truck Parts &

Salesperson: Amiee
3333 N Bolton Ave
Alexandria, LA 71303

Phone: 318-767-4287

Unit 5261**Notes:**

Mercedes-Benz MBE 900 Diesel

Type: Truck**Y/M/M:** 2004 Freightliner M2 112**VIN:** 1FVAC3DJ25HU35261**Odo:** 149,788**Job: 157334 40 PT INSPECTION****Correction:** SAFETY INSPECTION:

RIGHT HEADLIGHT OUT
TOP MARKER LIGHT
MISSING LIGHT IN FRONT
MISSING BRAKE LIGHT
AIR LEAK FROM AIR DRYER FILTER
GEAR BOX (OIL AROUND IT)
LEFT STEER WHEEL SEAL
RIGHT REAR DUST SHEILD FALLING APART
PLAY IN SWING BEARING
REAR DIFF LEAK

Job Labor

150.00

Job Total**150.00****Job: 157335 FULL PM SERVICE**

Correction: Drained oil , replaced both oil filters and both air filters, greased truck and topped off truck with 33 quarts of 15w40 oil , I did a 40 point inspection & listed the important issues i seen on unit and i installed the pm sticker in truck
Truck cranks as should and oil level is topped off

Job Labor

310.00

Job Parts

<u>Part</u>	<u>Qty</u>	<u>Price</u>	<u>Amount</u>
'AIR FILTER ' "	1	86.50	86.50
'OIL FILTER', "	1	21.41	21.41
'15W40 OIL PREFERRED', 'New'	9	15.20	136.80
'JT6HT - GREASE HI-TEMP RED TUBE - MYSTIK - BULK', "	1	4.50	4.50
'cab filter', "	1	17.45	17.45
'OIL FILTER', 'New'	1	53.57	53.57
'FUEL FILTER', "	1	49.43	49.43
'FUEL FILTER', "	1	26.40	26.40

Job Parts Total**396.06**

EPA Charges: Enviro

25.00

Shop Fee	31.00
Job Total	762.06

Job: 157337 DIAG HARD START SEE INTERNAL

Correction: 5/13/25 Looked over the unit. Found it took around an hour to be hard to start. Began searching for a relief valve but didnt find one. Was able to remove the primary fuel filter and found it was black and really dirty. Got new filters an found they were wrong. Once the new ones came in I installed both filters. I filled both filters with clean Got the unit started back will need to recheck in the morning.

5/14/25 Got keys out of office and went to the truck, pulled hood over and checked for any noticable leaks. No leaks seen, i then cranked over the truck and it cranked with-in the first few spins. Pulled truck into shop to start on the PM Service	
Job Labor	202.50
Job Total	202.50

Price	1,114.56
Total Tax	117.03
Grand Total	1,231.59